

Huey Yon (LKKAuto)

From: Rasul (LKKAuto)
Sent: Friday, 13 January 2023 10:09 AM
To: SUR; CS A Team
Subject: FW: CB 8261P

From: unitedcb@singnet.com.sg <unitedcb@singnet.com.sg>
Sent: Friday, 13 January 2023 10:08:40 am (UTC+08:00) Kuala Lumpur, Singapore
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: RE: CB 8261P

Dear Rasul

OK agree. Thank you

Regards
Ah Siang

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Friday, 13 January 2023 10:02 AM
To: unitedcb@singnet.com.sg
Cc: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>
Subject: CB 8261P

Hi Mdm,

refer to attachment

Audit checked some parts need verification.

We will be advising our principal a cost of repair P/P \$10,683.00./- with 05 days of repair, subject to their approval.

Kindly acknowledge

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315



Save the Earth. Print only when necessary.