




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER SINGAPORE 048623			Ref: CS3/SMO22012162/Uny3e2 Date: 13/12/2022 Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLN 9494H	Veh. Inspected	SMY 8552K	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2204428/SYH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	05/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (A)	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	JHMF4620AS200152	Colour	BROWN	
Odometer	98872 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	HABILEAD	6 mm	
L/H Front Tyre	215/45 R17	HABILEAD	6 mm	
R/H Rear Tyre	215/45 R17	GITI	6 mm	
L/H Rear Tyre	215/45 R17	GITI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/12/2022	Inspect Date / Time	06/12/2022 (12:15 PM)	
Survey held at	SHIFTER AUTO GARAGE PTE LTD 3016 BEDOK NORTH AVENUE 4 #07-04 EASTECH SINGAPORE 489947			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

Report Ref No. CS3/SMO22012162/Uny3e2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.