

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E**05 DEC 2022**

Estimate No. : **b1 64258**
Date Estimated : **05/12/2022**
Prepared By : **Han Kwan Yong**

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Fullmer Michael Keith
53 Pipit Road
#06-96

Singapore 370053**- ACCOUNT - 40000**

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJP2598B	WBA5A52010D823541	13/05/2015	5281A	39982

DESCRIPTIONVALUE

To replace rear bumper, left rear fender, left trunk floor panel including to pull & straighten rear left fender before cutting and to knock out dented area

5,950.00

To respray rear bumper, left rear fender, left roof frame, tail panel and boot compartment

3,645.00

To carry out body cavity preservation.
(For cut panel).

531.00

To remove and install boot compartment carpet and garnish to facilitate repair.

271.00

To remove and install rear windscreen glass to facilitate repair.

574.00

To supply and install rear windscreen solar film.

531.00

To remove and install wire harness, control units and battery at the rear section to facilitate panel replacement.

531.00

To check electrical wiring system and lighting at the rear section for proper function.

177.00

Sundries.

150.00

Total Labour 1: **12,360.00**

DESCRIPTIONQTYPRICVALUE

PLASTIC NUT FOR COARSE THREADED PIN

10**0.85****8.50**

EXTENSION FOR REAR LH WHEEL

1**1,099.10****1,099.10**

RR LH FENDER

1**2,232.65****2,232.65**

REINFORCEMENT PLATE C PILLAR LH

1**54.80****54.80**

REINFORCEMENT PLATE ROCKEL PANEL LH

1**54.80****54.80**

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 64258**
Date Estimated : **05/12/2022**
Prepared By : **Han Kwan Yong**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJP2598B	WBA5A52010D823541	13/05/2015	528iA	39982

DESCRIPTION	QTY	PRIC	VALUE
T WELD BOLT L=5.4MM	10	0.90	9.00
# RR LH MOUNT	1	199.70	199.70
# RR RH MOUNT	1	199.70	199.70
# REAR BUMPER PRIMED (PDC)	1	1,616.00	1,616.00
# RR WINDOW GREEN	1	882.65	882.65
# RR LH LIGHT IN THE SIDE PANE	1	638.00	638.00
BLIND RIVET AVIBVLB	15	0.55	8.25
SCREW (SF PLUS M5X15)	5	0.60	3.00
PUNCH RIVET N5	20	0.55	11.00
(DG) BODYWORK ADHESIVE K5A (50ML)	1	121.90	121.90
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
PUNCH RIVET N4	2	0.55	1.10
(DG/SL) BODY ADHESIVE K5 (195 ML)	1	353.50	353.50
(DG/SL)ADHESIVE PRIMER VP 206 (30ML)	1	27.85	27.85
(SL/DG) SEALANT D2 290ML	3	32.10	96.30

Total Parts : **7,907.05**

Labour 1	:	12,360.00
Parts	:	7,907.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,418.69
Grand Total	:	21,685.74

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **