

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO :  
REFERENCE : INS/IC/CHI/0268/2022  
DATE : 05-DEC-2022

ALLIANZ INSURANCE COMPANY OF SINGAPORE PTE LTD  
3 TEMASEK AVENUE  
#09-01 CENTENNIAL TOWER  
S(039190)  
TEL : 6297 2529  
FAX : 6395 3768/6297 1956

OWNER'S NAME : LI YULONG  
ADDRESS : APT BLK 274B COMPASSVALE BOW  
#14-525  
S(542274)  
TELEPHONE NO : 9021 6359

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 1  
VEHICLE NO : SLB2539Y  
MODEL CODE : GP3EKDC  
MODEL/YEAR : XV 1.6I-S AWD CVT  
ENGINE NO : FB16Y112284  
CHASSIS NO : JF1GP3KC5GG164884  
MILEAGE : 1 KM  
DATE IN : 05/12/2022  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : DENNIS LEONG JIA HUI  
ACCIDENT DATE : 05/12/2022

Print Date : 05/12/2022  
Print Time : 19:04:55

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLB2539Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST ALLIANZ INS (SMN2559P)		
2	ZZ/001	DOA:03/12/2022 TIME:1930 HRS LOCATION:278 COMPASSVALE BOW CARPARK DECK 2A		
3	ZZ/002	REPLACE FRONT HOOD, FRONT BUMPER, ENERGY ABSORBER, LH FENDER & SUPPORT PANEL <i>e60x3</i>	<del>3100.00</del>	<i>1800</i>
4	ZZ/003	RESPRAY FRONT HOOD, FRONT BUMPER, LH FENDER AND SUPPORT PANEL <i>e520x3</i>	<del>2160.00</del>	<i>1560</i>
5	ZZ/004	REMOVE & REFIX FRONT HEADLAMP WASHER & PIPING	<del>150.00</del>	<i>3860</i>
6	ZZ/005	REMOVE & REFIX A/CON CONDENSER & RADIATOR TO FACILITATE REPAIR	<del>220.00</del>	<i>+</i>
7	ZZ/006	A/CON GAS & COOLANT	<del>100.00</del>	<i>520-Suppl = 4380</i>
8	ZZ/007	4 WHEEL ALIGNMENT	<del>220.00</del>	
9	ZZ/008	TRANSFER/BALANCE TYRE/RIMS	<del>50.00</del>	
10	ZZ/009	TO CONDUCT (FRONT) LIGHTING TEST	<del>50.00</del>	
11	ZZ/011	SUNDRIES	<del>100.00</del>	<i>20</i>
12	ZZ/10	FAULT DIAGNOSTIC (RESET)	<del>280.00</del>	
TOTAL LABOUR CHARGES			6430.00	

\*Supplementary LABOUR

RESPRAY FRONT LH DOOR PANEL

\$520.00 ✓

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLB2539Y

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 DISC WHEEL AL 17 C67 <i>Xnn</i>	28111FJ170	1500.00			
2 RAD PNL COMPL RPR <i>repair</i>	53029FJ0009P	536.50			
3 FENDER F XUV LH <i>bu</i>	57120FJ0619P	203.50	✓		
4 HOOD COMPLETE-FRONT <i>Xnn</i>	57229FJ0009P	555.00			
5 BUMPER FACE F XUV <i>de</i>	57704FJ070	425.50	✓		
6 ENR ABSORB FOAM XU <i>cm</i>	57705FJ010	81.40	✓		
7 BRKT FRH BUMP CORN <i>? Xnn</i>	57707FJ001 <i>ns</i>	44.40			
8 BRKT FLH BUMP CORN <i>cm</i>	57707FJ011 <i>ns</i>	44.40	✓		
9 BRKT BUMP FRH <i>Xnn</i>	57707FJ140 <i>ns</i>	7.40			
10 BRKT BUMP FLH <i>cm</i>	57707FJ150 <i>n/s</i>	7.40	✓		
11 BACK BEAM COMPL-F <i>bt</i>	57711FJ0519P	266.40	✓		
12 COVER HOOK F <i>Xnn</i>	57731FJ460 <i>n/s</i>	4.80			
13 LAMP ASSY HEAD EHL <i>bu</i>	84001FJ630	876.90	✓		
14 TANK <i>cm</i>	86631FJ120	74.00	✓		
15 CLIP 2 PCS <i>ne</i>	909140062	6.00	✓		
16 GARNISH FRONT FENDER LH <i>de</i>	91112FJ111	185.00	✓		
SUB TOTAL		4818.60	0.00	0.00	0.00
LESS DISCOUNT ( NETT-20 %)		963.72	0.00	0.00	0.00
GRAND TOTAL		3854.88	0.00	0.00	0.00
OVERALL TOTAL		3854.88			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

**\*Supplementary Parts**

MUD GUARD ASS F LH \$111.00 ✓ NEC

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLB2539Y

TOTAL LABOUR CHARGES	6430.00
TOTAL SPARE PARTS CHARGES	3854.88
	-----
GRAND TOTAL	10284.88 *
	-----

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :  
SURVEYED DATE :  
AUTHORIZED DATE :  
EXCESS CLAUSE :  
LIABILITY :  
REMARKS :

Rasul - Hp 90010068  
07/12/22 @ 1200  
6 days  
Resurvey before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: