



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22012198/Dny3m4 Date: 11/01/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKE 86X	Veh. Inspected	SLF 2491D	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS22/3392	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	05/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CLA180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	WDD1173422N345745	Colour	BLACK	
Odometer	135808 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	GOODYEAR	5 mm	
L/H Front Tyre	225/40 R18	GOODYEAR	5 mm	
R/H Rear Tyre	225/40 R18	GOODYEAR	5 mm	
L/H Rear Tyre	225/40 R18	GOODYEAR	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/12/2022	Inspection Date	14/12/2022	
Survey held at	JWG INTERNATIONAL PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)REGISTRATION DATE: 19 AUG 2016 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	