



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22012201/Kwy3e2 Date: 29/12/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMJ 2980B	Veh. Inspected	SKZ 7653C	
Policy No.	P10611363R00	Coverage (\$)	0.00	
Claim No.	C10019068/JL	Excess (\$)	0.00	
Assign From	SALIZAWATI HAIZAR	Assign Date	06/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS C (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDKD3B3301116115	Colour	METALLIC SILVER	
Odometer	90698 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	4 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	4 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	5 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/12/2022	Inspection Date	19/12/2022	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		