

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
74 KIAN TECK ROAD
SINGAPORE 628800

Officer in Charge : VIVIAN TAN EE WI
Tel :
Email :

Customer :

GRAB RENTALS PTE LTD
3 MEDIA CLOSE #07-03
SINGAPORE 138498

Attn :
Tel :
Fax No. :

Quotation No. : QO22/12-1018	Quotation Date : 02/12/2022	Terms : 60 DAYS
Vehicle No. : SLS5202J	Chassis No. : JM6BN22A8H0160460	Policy Number : A29069774MKF
Model : MAZDA 3		Date of Accident : 02/12/2022
Third Party Insurer :		TP Vehicle No. : QX232U
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER <i>de</i>	1	1,175.0000	1,175.00 ✓
2	REAR BUMPER CLIPS @ 10PCS <i>m</i>	10 <i>1209</i>	4.0000	40.00 ✓
3	REAR BUMPER TOW COVER @ 2PCS <i>1pc m/s</i>	2 <i>1209</i>	55.0000	55 110.00
4	REAR BUMPER RIVET @ 4PCS <i>m</i>	4 <i>1032</i>	5.0000	20.00 ✓
5	REAR REINFORCEMENT <i>? x m</i>	1	545.0000	545.00
6	LESS 20%	1	-378.0000	-378.00
7	REAR REVERSE SENSOR @ 1SET <i>? x m</i>	1	280.0000	280.00 <i>200?</i>
8	TO REMOVE & REPLACED REAR REVERSE SENSOR.	1	120.0000	40 120.00
9	TO KNOCKING & PANEL BEATING.	1	600.0000	200 600.00
10	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.	1	500.0000	200 500.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1032
440
1472
10%
1177.60
\$1,150 / 2 days

Rasm
Hp 90010068
2 days
4s
08/12/22 @ 1355
Resurvey after repair

440

Sub Total 3,012.00
GST(7.00%) 210.84
Total (SGD) 3,222.84

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800