$51~\mathrm{UBI~AVE~1}, \#02-25~\mathrm{PAYA~UBI~INDUSTRIAL~PARK}, \mathrm{SINGAPORE~408933~TEL:} \\ (065)~62563561~\mathrm{FAX:} \\ (065)~62564315$

Immediate Advice

To: HSBC Life (Singapore) Pte. Ltd. Date: 20/02/2023

Survey Details:

Date of loss	19-Nov-2022
Date of appointment	6-Dec-2022
Date of survey	8-Dec-2022
Location of survey	SOON SENG COMPANY SG PTE LT

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM		
Vehicle number	GBK3522J		
Make and Model	TOYOTA DYNA 150 5MT		
Date of registration	19-May-20		
Market Value	\$ 85,000.00		
Parf Rebate	\$ 16,353.00		
Nett Loss	\$ 68,647.00		

Repair details:

Initial Estimate 17,702.00

Proposed/Revised repair cost:

Parts	\$ 2,422.73
Check items (estimate)	NIL
Labour	\$ 995.00
Total	\$ 3,417.73
Lump Sum(if applicable)	\$ 2,700.00

Number of days for repair	4.0	(est)
itamice of autorior repair		(000)



 $51\,UBI\,AVE\,1, \#02-25\,PAYA\,UBI\,INDUSTRIAL\,PARK, SINGAPORE\,408933\,TEL: (065)\,62563561\,FAX: (065)\,62564315$

Remarks:

OID REAR-ENDED TP.			

Mandate:

Liability(TP)	100%		
Proposed repair cost	\$	2,700.00	\$ 2,700.00
Loss of use (6DAYS X \$100.00)	\$	600.00	NIL
Loss of rental (6DAYS X			
\$100)(W/GST)		NIL	\$ 642.00
Loss of income		NIL	NIL
LTA search fees	\$	7.45	\$ 7.45
Others		NIL	NIL
Proposed Total	\$	3,307.45	\$ 3,349.45