

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHB2337K
MAKE HYUNDAI
MODEL IONIQ

DATE: 03.12.22
MVA JUMANI
DOA: 02.12.22

CLIPSUM)
INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	REAR BUMPER ASSY			\$459.40	✓ CRK
1	REAR BUMPER CENTRE MOULDING			\$451.25	✓ DEF
1	REAR BUMPER BEAM			\$394.80	?
10	REAR BUMPER CLIPS			\$22.00	✓ NEL
1	BOOTLID EMBLEM – IONIQ			\$31.30	✓ NEL
1	BOOTLID EMBLEM – HYBRID			\$24.30	✓ NEL
1	BOOTLID EMBLEM – H			\$28.00	✓ NEL
1	REAR BUMPER LOWER CENTRE MOLDG			\$155.00	?
1	REAR BUMPER STAY - LH			\$138.10	?
1	REAR BUMPDER STAY - RH			\$138.10	?
1	REAR BUMPER TOW COVER			\$98.80	EX SVL
	SUB TOTAL			\$1,941.05	
	LESS 20%			\$388.21	
	DISCOUNTED TOTAL			\$1,552.84	
	REVERSE SENSOR			\$180.00	NET X SVL
	REAR BOOTLID COMFORT LOGO			\$30.00	NET / NEL
	REAR BOOTLID TEL.NOS LOGO			\$30.00	NET / NEL
	REAR BOOTLID APPS LOGO			\$40.00	NET / NEL
	REAR BUMPER MAT			\$50.00	NET / NEL
				\$330.00	
	Labour Charge				
	PANEL BEATING			\$700.00	300
	SPRAY PAINT			\$600.00	250
	REMOVE / REFIX REVERSE SENSOR			\$50.00	30
	CHECK WIRING			\$50.00	X NN
	TOTAL LABOUR			\$1,400.00	
	ESTIMATE TOTAL			\$3,282.84	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants is hereby notified
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for painting
- Parts prices are subject to confirmation
- Third party survey is not allowed without Prejudice
- No illegal modification is allowed
- Supplementary (mistake) the resurveyed and any is subject to the approval of the Insurance Company

Acknowledged by: _____
Date: _____

NA2 LKK
5/12/2022 1530
LIS
2 DAYS
CHECK ITEM PHOTO
AFTER REPAIR PHOTO