

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHB4789B

Date: 05.12.2022

Make : HYUNDAI

Insurance: INCOME

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	FRT BUMPER			\$ 481.10	✓cut
1	FRT BUMPER REINFORCEMENT			\$ 1,136.70	?
1	FRT BUMPER MOULDING CENTRE UPPER			\$ 368.50	?
10	FRT BUMPER CLIPS			\$ 22.00	✓WEL
1	HEADLAMP RH			\$ 2,110.30	✓SVC
1	FRT BUMPER TOWING COVER			\$ 29.00	✓SVC
	SUB TOTAL			\$ 4,147.60	
	LESS 20%			\$ 829.52	
	DISCOUNTED TOTAL			\$ 3,318.08	
					Nett
				\$ -	nett
	Labour Charge				
	PANEL BEATING			\$ 400.00	350
	SPRAY PAINTING CHARGE			\$ 300.00	250
	CHECK ALL LIGHTING			\$ 60.00	✓NN
	TOTAL LABOUR			\$ 700.00	
	Emblem-Blue Drive (LH/RH)				
	ESTIMATE TOTAL			\$ 4,018.08	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NA2 LKK
 5/12/2022 1620
 LIS
 2 DAYS
 CHECK ITEM PHOTO
 AFTER REPAIR PHOTOS

Auto Consultants hence notify
 Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: