

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)**
CTPL

[Loke Wei Yiang](#)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	06/12/2022
Vehicle Reg. No.:	SH9120K	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	17/03/2017
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEGU329699	Chassis No:	KMHC851CVHU022742
Odometer:	900202 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,961.52
Miscellaneous Items	11.00
Labour	780.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,752.52
+ GST 7.00% (S\$)	192.68
Nett Amount (S\$)	2,945.20

This claim is handled by: **MS. LOKE YY**

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 07 Dec 2022)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SH9120K/07/12/2022 09:25**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	20.00	0.00	*459.40 FL <i>/BUC</i>
2	1		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL <i>XNN</i>
3	1		*REAR BUMPER CENTRE MOULDING ASSY	20.00	0.00	*451.25 FL <i>/BUC</i>
4	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	*394.80 FL <i>?XSVL</i>
5	1		*REAR BUMPER REINFORCEMENT BRACKET LH	20.00	0.00	*138.10 FL <i>?/BT</i>
6	1		*REAR BUMPER REINFORCEMENT BRACKET RH	20.00	0.00	*138.10 FL <i>?/BT</i>
7	1		*ANTENNA SMARTKEY	<i>/CRA</i> 20.00	0.00	*40.50 FL <i>*CRA</i>
8	1		*REAR BUMPER FOG LAMP	<i>/CRA</i> 20.00	0.00	*201.50 FL <i>XNN</i>
9	1		*RENEW ADVERTISEMENT STICKER	0.00	0.00	*200.00 F <i>/NEC</i>
10	1		*REAR NUMBER PLATE WITH TRIM COVER	0.00	0.00	*55.00 F <i>/CRA</i>
11	1		*REAR BUMPER REVERSE SENSOR	0.00	0.00	*180.00 FX <i>SL</i>
12	1		*REAR BUMPER RUBBER MAT	0.00	0.00	*50.00 F <i>/NEC</i>

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,229.35	2,330.65
- List Item Discount on L Items (\$\$)		369.13
Total Parts (\$\$)	981.88	1,961.52

ComfortDelGro Engineering Pte Ltd/SH9120K/07/12/2022 09:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

728.52

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	400.00 350
2	SPRAY PAINTING CHARGE	New	300.00 250
3	REMOVE/REFIX REVERSE SENSOR	New	80.00 30
Gross Labour Cost (S\$)			780.00

ComfortDelGro Engineering Pte Ltd/SH9120K/07/12/2022 09:25. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

NA2 LKK
 7/12/2022 1530
 LIS
 2 DAYS
 CHECK ITEM (PHOTO)
 AFTER REPAIR PHOTOS

1,927.50

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: