

POH LEE REPAIR & SERVICING OF VEHICLES

No. 3 Joo Koon Road (S628967)
Tel : 6862 9691 Fax : 68629693
ROC No.: 52799345W

Our Ref: TP/PC3716T/8151

23/11/2022

Poh Lee Bus Transport Pte Ltd
3 Joo Koon Road
Singapore 628967

QUOTATION

Dear Sir,

DOA :14/11/22

Cost of Repair to Vehicle PC3716T

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Rear Bumper	1	2,200.00	2,200.00
2.	Spray Painting on Rear affected portion with artwork	1	1,000.00	1,000.00
3.	Labour & Misc. Charges: To remove the affected parts & all relevant attachment & fittings to commence repairs; cut & weld the necessary parts as listed above; panel beat & reshapes the affected areas; replace the damaged components, reinstall & realign all necessary parts	1	1,400.00	1,400.00
	SUB-TOTAL			S\$4,600.00

Thanks you.

Yours faithfully,

Eddie Ong