



WICKED WORKS GARAGE PTE LTD

Blk 13 Kaki Bukit Road 4

#01-04 Bartley Biz Centre Singapore 417807

general.wickedorks@gmail.com

HP : 9004 0057

3-Jan-23

REG NO. : SJH5632H

MAKE/MODEL: HONDA JAZZ/FIT

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

<u>QTY</u>	<u>DESCRIPTION</u>	<u>AMOUNT(S\$)</u>
<u>LIST ITEMS</u>		
1	FRONT - BUMPER WITH GRILLE	\$ 300.00
1	L HEAD LIGHT	\$ 250.00
1	RADIATOR + CONDENSER	\$ 300.00
1	FRONT - BAR	\$ 100.00
1	SUPPORT CUT	\$ 850.00
		\$ 1,800.00
LESS 20%		\$ 1,500.00
<u>S/N</u>	<u>LABOUR CHARGES</u>	
1	TO REMOVE, REPLACE DAMAGED LIGHTS AND CHECK REAR WIRING	\$ 120.00
2	TO REMOVE AND REPLACE RADIATOR AND CONDENSER	\$ 200.00
3	TO REMOVE AND REPLACE SUPPORT CUT	\$ 200.00
4	TO CONDUCT WHEELALIGNMENT	\$ 150.00
5	TO APPLY UNDERCOATING	\$ 150.00
6	PANEL BEATING	\$ 650.00
7	TO RESPRAY PAINTING ON AFFECTED AREAS	\$ 500.00
		\$ 1,970.00
GRAND TOTAL :		
		\$ 3,470.00