



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22012260/Rny3m4 Date: 26/01/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 4886Z	Veh. Inspected	SJQ 6951H	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/11/22/2052	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	07/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS E AUTO	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053HY9305111790	Colour	GREY	
Odometer	238987 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60R15	GRENLANDER	6 mm	
L/H Front Tyre	185/60R15	GRENLANDER	6 mm	
R/H Rear Tyre	185/60R15	GRENLANDER	6 mm	
L/H Rear Tyre	185/60R15	GRENLANDER	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/11/2022	Inspection Date	12/12/2022	
Survey held at	RICKY TEO BATTERY & TYRES TRADING BLK 1002 BUKIT MERAH LANE 3 #01-91 SINGAPORE 159719			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	