

(08/11/13) wet

ASS. REC. BY: AME

REF:

CCY/GRS 22012262/Rpa3

249c

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFU 17714at Workshop m/s MOTOR IMAGEof 25, LENH KEG RD

Insured:

111

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

2pm

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

87K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lump Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

REPAIR LIMIT - 56K

Veh No:

SFU 17714

Yr Regn:

2018 / Jan

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

SUBARU FORESTER 2011-LSP cc 1985

Colour:

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading:

099673

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JFS1 J5K535110205

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

05/12/22

D.O.I.

09/12/22

Survey held at

MOTOR IMAGEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prel. Report



: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$

) \$ + RS. \$1



: Interview (\$

) Photos



: Tech. Invs (\$

) Others



: Weekend (\$

) TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0271/2022
DATE : 07-DEC-2022

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#05-00
IOB BUILDING S(049711)
TEL : 63476100
FAX : 62244174

OWNER'S NAME : WONG KAI JUAN(HUANG KAIZHUANG)
ADDRESS : 238 WESTWOOD AVENUE
#12-41
S(648363)
TELEPHONE NO : 9687 7359

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : -
VEHICLE NO : SFU1771U
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YD92313
CHASSIS NO : JF1SJ5KC5JG110205
MILEAGE : 1 KM
DATE IN : 07/12/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 07/12/2022

Print Date : 07/12/2022
Print Time : 09:40:19

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFU1771U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST INDIA INT INS (SLP8933D)		
2	ZZ/001	DOA:05/12/2022 TIME:1131 HRS LOCATION:DOVER ROAD TOWARDS AYE		
3	ZZ/002	REPLACE REAR BUMPER,BUMPER BEAM,END PANEL AND TAILGATE @600 X 2	2480.00	1800 1200
4	ZZ/003	RESPRAY REAR BUMPER,BUMPER BEAM,END PANEL AND TAILGATE / @520 X 2	2160.00	1080
5	ZZ/004	TRANSFER (TAILGATE) MECHANISM	150.00	
6	ZZ/005	SUPPLY AND REPLACE REVERSE SENSOR - 2EYES	300.00	80
7	ZZ/006	TO CONDUCT (REAR) LIGHTING TEST	50.00	X
8	ZZ/007	TO CONDUCT WATER SEEPAGE TEST	100.00	
9	ZZ/008	FAULT DIAGNOSTIC (RESET)	280.00	
10	ZZ/009	TO CONDUCT (REAR) PROTECTANT COATING	500.00	280?
11	ZZ/011	SUNDRIES	100.00	20
12	ZZ/10	TO CONDUCT (REAR) ANTI-RUST COATING	580.00	280?
TOTAL LABOUR CHARGES			6700.00	

AFTER MARKET AUTO TAILGATE CANNOT LOCK

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFU1771U

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				S/LIST REMARKS
		NETT	LIST	S/NETT		
1 SKIRT COMPL REAR END PANEL <i>9</i>	52401SG0109P	296.00				
2 BUMPER FACE REAR FORESTER IL <i>de</i>	57704SG012	555.00				
3 BRKT SD R RH <i>ne</i>	57707SG080	14.80				
4 BRKT SD R LH <i>x</i>	57707SG090	14.80				
5 BEAM COMPL R EU <i>?</i>	57711SG0219P	296.00				
6 COVER HOOK R <i>mis</i>	57731SG010NN	13.00				
7 COVER BMPR R (EXHAUST) <i>sur</i>	57731SG060	14.80				
8 PANEL CPL R/G NA <i>4</i>	60809SG0109P	1102.60				
9 GLASS R/G <i>ne / photo?</i>	63019SG000	821.40				
10 RUBBER DAM GLS X2PCS <i>ne</i>	63232SG000	7.40				
11 CLIP BMPR * 9 PCS <i>ne</i>	909140007	21.60				
12 CLIP *2 PCS <i>ne</i>	909140062	6.00				
13 LETTER MARK FORESTOR R <i>ne</i>	93079SG000	40.70				
14 LETTER MK R SUB <i>ne</i>	93079SG030	66.60				
15 CARGO STEP PANEL (RESIN)FORESTER <i>com</i>	E775ESG000	420.00				
SUB TOTAL		3690.70	0.00	0.00		0.00
LESS DISCOUNT (NETT-20 %)		738.14	0.00	0.00		0.00
GRAND TOTAL		2952.56	0.00	0.00		0.00
OVERALL TOTAL		2952.56				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFU1771U

TOTAL LABOUR CHARGES	6700.00
TOTAL SPARE PARTS CHARGES	2952.56
GRAND TOTAL	9652.56 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME : Rasue - Hp 90010068
SURVEYED DATE : 09/12/22 @ 1400
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00 5 days
LIABILITY : 0.00
REMARKS : Resay before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	249C

Vehicle Details

Vehicle No.:	SFU1771U
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Dec 2022
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0i-L CVT AWD SR
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	FB20YD92313
Chassis No.:	JF1SJ5KC5JG110205
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,559.00
Original Registration Date:	26 Jun 2018
First Registration Date:	26 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$13,559.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jun 2028
PARF Rebate Amount:	\$10,169.00

Intended COE Rebate Details

COE Expiry Date:	25 Jun 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,000.00
COE Rebate Amount:	\$19,940.00
Total Rebate Amount:	\$30,109.00

Subaru Forester 2.0i-L Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price

\$87,800

Depreciation ⓘ

\$14,610 /yr

[View models with similar depre](#)

Reg Date

27-Jun-2018

(5yrs 6mths 15days COE left)

Mileage

89,000 km (20k /yr)

Manufactured ⓘ

2018

Road Tax ⓘ

\$1,208 /yr

Transmission

Auto

Dereg Value ⓘ

\$30,132 as of today (change)

OMV ⓘ

\$13,559

COE ⓘ

\$36,000

ARF ⓘ

\$13,559

Engine Cap

1,995 cc

Power

110.0 kW (147 bhp)

Curb Weight ⓘ

1,591 kg

No. of Owners ⓘ

1

Type of Vehicle

SUV