



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SND1034J Honda Vezel PI New Model RV3

			Estimated
No	Qty	Parts Description	Parts Price
1	1	Rear bumper assy	\$ 1,208.00
2	1	Rear bumper left bracket	\$ 75.00
3	1	Rear bumper right bracket	\$ 75.00
4	1	Rear bumper left reflector	\$ 98.00
5	1	Rear bumper right reflector	\$ 98.00
6	1	Rear bumper tow cover	\$ 88.00
7	2	Side cover x2pc	\$ 400.00
8	1	Lower lip	\$ 850.00
9	1	Lower lip tray trim cover	\$ 450.00
10	1	Rear center center chrome	\$ 500.00
11	1	Rear tailgate assy	\$ 1,750.00
12	1	Rear tailgate centre logo	\$ 85.00
13	1	Rear tailgate emblem	\$ 68.00
14	1	Rear tailgate weatherstrip	\$ 280.00
15	1	Rear tailgate lock mechanism /auto electric lock	\$ 380.00
14	1	Rear end top garnish	\$ 280.00
15	1	Rear tailgate inner trim board	\$ 330.00
16	3	Rear tailgate inner side garnish cover	\$ 300.00
17	2	Rear tailgate no plate lamp	\$ 180.00
18	1	Rear tailgate left taillamp	\$ 985.00
19	1	Rear tailgate right taillamp	\$ 985.00
20	1	Rear left taillamp	\$ 785.00
21	1	Rear right taillamp	\$ 785.00
22	2	Rear tailgate damper	\$ 400.00
23	1	Rear end lower panel	\$ 850.00
24	1	Exhaust	\$ 800.00
25	1	Keyless sensor	\$ 285.00
26	1	Tailgate auto switch	\$ 295.00
27	1	Rear harness	\$ 650.00
Parts Sub-total			\$ 9,493.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SND1034J Honda Vezel PI New Model RV3

			Estimated
No	Qty	Parts Description	Parts Price
<u>Special Nett Items</u>			
1	10	Rear bumper clips	\$ 80.00
2	8	Rear end lower panel top garnish clips	\$ 80.00
3	1	Rear end lower panel sealant	\$ 120.00
4	8	Rear tailgate inner trim board clips	\$ 50.00
5	6	Rear tailgate outer garnish clips	\$ 50.00
6	1	Rear floor panel sealant	\$ 120.00
7	1	Rear windscreen glass sealant	\$ 80.00
8	10	Rear windscreen inner side garnish clips	\$ 80.00
9	4	Rear bumper reverse sensor	\$ 800.00
10	1	Rear no plate with casing	\$ 80.00
24	1	Rear windscreen glass rubber seal	\$ 105.00
Special Nett Items			\$ 1,075.00