

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jenny Lew

Date: 23 Mar 2023

**Preliminary Advice**

|                    |                                                                                                                    |                         |              |
|--------------------|--------------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SMV9834G                                                                                                         | Accident Date           | : 07/12/2022 |
| TP Vehicle No      | : SLV7411T                                                                                                         | Assignment Date         | : 08/12/2022 |
| Make               | : HYUNDAI ELANTRA                                                                                                  | Est. Duration of Repair | : 6          |
| Date of Inspection | : 08/12/2022                                                                                                       |                         |              |
| Inspection At      | : HUA MENG SPRAY PAINTING WORKSHOP (HQ)<br>NO 1 KAKI BUKIT AVENUE 6, #01-61 AUTOBAY@KAKI BUKIT<br>SINGAPORE 417883 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 12,012.00 |
| Revised Amount              | :S\$ | 7,119.36  |
| Check Items (Estimated)     | :S\$ | 0.00      |
| Total                       | :S\$ | 7,119.36  |

|                 |      |          |
|-----------------|------|----------|
| Lump Sum Repair | :S\$ | 5,700.00 |
|-----------------|------|----------|

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.