



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

HSBC LIFE (SINGAPORE) PTE LTD

INV No. AC2301528

10 MARINA BOULEVARD

INV Date 14/03/2023

#48-01 MARINA BAY FINANCIAL CENTRE

Reference CS3/ASM22012305/Gqp3e2

TOWER 2

Code HSB

SINGAPORE 018983

ATTN: LOW GARNET

#### PROFESSIONAL SERVICE FEE

Vehicle No. SKU 4596E

Insured Veh. SHA 1185T

Claim No. S2M04G5S

Policy No. VFX/P2419138

Accident Date 06/12/2022

Inspection Date 09/12/2022

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 09.12.2022)	
Repaired vehicle before return to claimant as per NIMA Protocol (Photo taking + Transport on 13.12.2022)	
<b>Subtotal</b>	<b>100.00</b>
<b>GST (8%)</b>	<b>8.00</b>
<b>Grand Total</b>	<b>108.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

**KHM**