



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

HSBC LIFE (SINGAPORE) PTE LTD

INV No. AC2301942

10 MARINA BOULEVARD

INV Date 29/03/2023

#48-01 MARINA BAY FINANCIAL CENTRE

Reference CS3/ASM22012308/Tvp3e2

TOWER 2

Code HSB

SINGAPORE 018983

ATTN: LOH CYNTHIA

PROFESSIONAL SERVICE FEE

Vehicle No. FBQ 5000D

Insured Veh. SH 8044D

Claim No. S2M04FWO

Policy No. VFX/P2419138

Accident Date 02/12/2022

Inspection Date 09/12/2022

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 13.12.2022)	
Repaired vehicle before return to claimant as per NIMA Protocol (Photo taking + Transport on 21.12.2022)	
Subtotal	100.00
GST (8%)	8.00
Grand Total	108.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM