



1

of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/LPC22007111/Rny3-1

LONPAC INSURANCE BHD

Ref: ~~CS3/LPC22007111/Toy3~~

300 BEACH ROAD

Date: ~~26/07/2022~~ 08/12/2022

#17-04/07 THE CONCOURSE SINGAPORE 199555

Code: LPC2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	YN 4109A	Veh. Inspected	GV 5411R
Policy No.		Coverage (\$)	0.00
Claim No.	21/22/22/VC05/026065	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	26/07/2022 08/12/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/07/2022	Inspection Date	27/07/2022
Survey held at	SHENG KHOON MOTOR SERVICE 393 WOODLANDS ROAD BLK D4 YEE TEE INDUSTRIAL ESTATE SINGAPORE 677972		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.