



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No : GV5411R

Report No. : PAS/TP/0370722

APPRAISEMENT SCHEDULE

S/No.	Parts/Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To remove, replace, realign refrigerated box LH side panel and rear door aluminium support frame. (Include supply refrigerated box LH side panel, rear door aluminium support frame and sealants)	\$ 2,500.00	1500 \$ 1,800.00
2	To spray painting, blending on affected and adjacent area.	\$ 1,200.00	800.00 500
3	To supply body sticker (Advertisement Graphics) film materials and wrap, apply on refrigerated box LH side panel.	\$ 1,200.00	1,000.00 700
Labour Total :		\$ 4,900.00	\$ 3,600.00
Total (Parts & Labour) :		\$ 4,900.00	\$ 3,600.00

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 2,880.00

Under normal circumstances, the repairs should be completed within a reasonable period of 7 Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

18 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.