


ASS. REC BY: Tauhin

REF: ALG

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: 1600
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 495K
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 12 days Res.: Yes or No
Lump Sum: 1-B.1 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: Neer Sanyal Vehicle: IN / OUT

Veh No: 5JR 32145 Yr Regn: 2018 June
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Indi A3 SB c.c. 999
Colour: Red A/C: Insured / Std / NI / NA
Sp. Reading: 29174 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: W144 ZZZ 8V8 J4115083
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modl: NI / SD / STD / AJR / or _____
Tyre Size: F: 205/55 R16
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 8/12/22
Survey held at Premium ubi
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
03/05/2023	Confirm final fig \$14,293.88 before excess \$600 & GST @ 12 repair days (Red \$6,289.12 / 31%)

Date/Time, File Pass to? 03/05/2023
1) Typist
Date/Time, File Return to? _____
2) _____

Days Of Repair: 12
Resurvey No. of Trip: _____

Rep. Format: OD
Lump Sum / L.B. / C. \$14,293.88

Add Fee: ☐ Site Insp (\$ _____)
☐ Interview (\$ _____)
☐ Tech. Invs (\$ _____)
☐ Weekend (\$ _____)

Survey Fee: _____	
Transportation: _____	
S + RS. Sl. _____	
Photos _____	
Others _____	
TOTAL _____	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/01092/2022/EQ
DATE : 7-Dec-22
WIP : 53547

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/12/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : DR SUYUN TANG
ADDRESS : BLK 107A EDGEFIELD PLAINS
#17-108
SINGAPORE 821107
TELEPHONE : HP +65 81003579
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800069536-04
VEHICLE NO : **SJR 3214 S**
MODEL CODE : AUDI A3 SPORTSBACK 1.0 TF
MODEL YEAR : 14/6/2018
ENGINE NO : CHZ 464327
CHASSIS NO : WAUZZZ8V8JA115083
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Dec-22
PLACE OF ACCIDENT : B2 CARPARK VIVO CITY


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJR 3214 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 350.00	✓
2	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	✓ photo.
3	TO RENEW LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR LOWER SECTION FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,500.00	2000 ✓
4	TO RESPRAY LHS REAR FENDER, LHS SILL PANEL, LHS REAR DOOR AND DOOR ENTRANCE. ✓ ✓ ✓	\$ 3,500.00	1925
5	TO RENEW LHS REAR RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 9,462.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJR 3214 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR SIDE PANEL - LH	1	\$ 4,445.00	bt ✓ 3,556.00
2	REAR WHEEL SPOILER - LH	1	\$ 39.00	? x } un
3	REAR WHEEL HOUSING LINER	1	\$ 260.00	? x } un
4	REAR DOOR - LH	1	\$ 2,973.00	bt ✓ 2,378.40
5	REAR OUTER DOOR SEAL - LH	1	\$ 179.00	ne ✓ 142.80
6	BONDING AGENT	1	\$ 51.00	? x }
7	CLEANING SOLUTION	1	\$ 74.00	? x }
8	APPLICATOR	1	\$ 9.00	? x }
9	REAR DOOR CATCH - LH	1	\$ 105.00	? x }
10	REAR DOOR INNER SEAL - LH	1	\$ 213.00	x }
11	REAR WINDOW REGULATOR - LH	1	\$ 286.00	? x }
12	REAR ALUMINIUM RIM	1	\$ 1,303.00	cut ✓ 1,042.40
13	REAR ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	ne ✓ 2.96
14	STONE CHIP	S/N	\$ 180.00	ne ✓
15	ACRYLIC SEALANT	S/N	\$ 180.00	ne ✓
16	CAVITY WAX	S/N	\$ 140.00	ne ✓
17	METAL FILLER POWDER	S/N	\$ 280.00	ne ✓
18	LHS REAR TYRE	S/N	TBC ?	x un
19	SUNDRIES		\$ 400.00	? 4.32 ✓ ne
TOTAL SPARE PARTS			\$ 11,121.00	
TOTAL LABOUR CHARGES			\$ 9,462.00	
GRAND TOTAL			\$ 20,583.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tan Kah 97495749
Not Authorise 2/12/22 C 10300-
EX: to be advise
Resurvey before paint
12 days
Tan Kah C 10300-0000

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	758E
Vehicle Details	
Vehicle No.:	SJR3214S
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Dec 2022
Vehicle Make:	AUDI
Vehicle Model:	A3 SPORTBACK 1.0 TFSI S TRONIC (LED)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	CHZ464327
Chassis No.:	WAUZZZ8V8JA115083
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,173.00
Original Registration Date:	14 Jun 2018
First Registration Date:	14 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$25,843.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jun 2028
PARF Rebate Amount:	\$19,382.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jun 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,426.00
COE Rebate Amount:	\$20,084.00
Total Rebate Amount:	\$39,466.00

The information contained herein is correct as at 08 Dec 2022

OK