



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22012329/Rvp3m4	
			Date: 20/06/2023	
			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SKS 8450B
	Policy No.	DHOM120050972001	Coverage (\$)	0.00
	Claim No.	M12D00162212	Excess (\$)	750.00
	Assign From	KATIE LEE	Assign Date	09/12/2022
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA3 4DR SEDAN 1.5L S/R	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JM6BM42A8G0309944	Colour	RED
	Odometer	101290 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60R16	YOKOHAMA	6 mm
	L/H Front Tyre	205/60R16	YOKOHAMA	6 mm
	R/H Rear Tyre	205/60R16	YOKOHAMA	6 mm
	L/H Rear Tyre	205/60R16	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	01/12/2022	Inspection Date	09/12/2022
	Survey held at	27A TANJONG PENJURU S609042 LEVEL 5		
	Repairer	VIN'S MOTOR PTE LTD		
5a. Remarks				
	A)THE MARKET VALUE IS S\$36,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	