



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811 ATTN:KITTY			Ref: CC4/ASM22012332/Apa3q2 Date: 11/05/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 616M	Veh. Inspected	SLU 8133U	
Policy No.	P2465703	Coverage (\$)	0.00	
Claim No.	S2M04G2Q	Excess (\$)	0.00	
Assign From		Assign Date	09/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN22A8J0176740	Colour	BLACK	
Odometer	132665 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	TOURADOR	6 mm	
L/H Front Tyre	205/60 R16	TOURADOR	6 mm	
R/H Rear Tyre	205/60 R16	TOURADOR	6 mm	
L/H Rear Tyre	205/60 R16	TOURADOR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/12/2022	Inspection Date	12/12/2022	
Survey held at	AUTO UNITED SG PTE LTD 13 KAKI BUKIT ROAD 4, #03-29, BARTLEY BIZ CENTRE, SINGAPORE 417807			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	