



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC22012335/Kvp3e2 Date: 05/01/2023 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SDA 9899L
	Policy No.	Z22VP05030835	Coverage (\$)	0.00
	Claim No.	22/22/22/VP05/026651	Excess (\$)	500.00
	Assign From	GERALD POH	Assign Date	09/12/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E250 (A)	c.c	1796
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	WDD2120472A618240	Colour	METALLIC BROWN
	Odometer	105647 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R18	TOYO	6 mm
	L/H Front Tyre	245/40 R18	TOYO	6 mm
	R/H Rear Tyre	245/40 R18	TOYO	6 mm
	L/H Rear Tyre	245/40 R18	TOYO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/11/2022	Inspection Date	09/12/2022
	Survey held at	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A) THE MARKET VALUE IS S\$113,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	