

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pauline Tham

Date: 13 Dec 2022

**Preliminary Advice**

Vehicle No	: SMP168L	Accident Date	: 06/12/2022
Make	: JAGUAR XF	Policy No.	: DMPCSNW00173622203
Assignment Date	: 09/12/2022	Excess	: S\$750.00
Date of Inspection	: 12/12/2022	Est. Duration of Repair	: 12
Inspection At	: DING AUTO PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	63,352.24
Revised Amount	:S\$	40,312.24
Check Items (Estimated)	:S\$	21,590.00
Total	:S\$	61,902.24
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,500.00
COE / PARF Rebate	:S\$	47,250.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,250.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Repairer asking for repair cost \$20,000.00

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .