



1 of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD
#09-01 SINGAPORE 068897

Ref: CS6/AIS22012348/Kvp3

Date: 09/12/2022

Code: AIS

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SMN 2559P
Policy No.	SP2002139009-01	Coverage (\$)	0.00
Claim No.	202220208654	Excess (\$)	1,100.00
Assign From	SHARON LIM	Assign Date	09/12/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	03/12/2022	Inspection Date	
Survey held at	CHENG HOE MOTOR SERVICE BLK 1019, YISHUN INDUSTRIAL PARK A #01-374 SINGAPORE 768761		

5a. Remarks

	A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--	--