



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS3/AIS22012358/Tvp3e2	
			Date: 27/03/2023	
			Code: AIS	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SKE 9088G	Veh. Inspected	SKX 8769G	
Policy No.		Coverage (\$)	0.00	
Claim No.	2022 22008714KC	Excess (\$)	0.00	
Assign From	SHANTI	Assign Date	09/12/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WVWZZZAUZFW180970	Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/12/2022	Inspection Date	09/12/2022	
Survey held at	EMPIRE GARAGE PTE LTD 10 KAKI BUKIT ROAD 2, #01-35, FIRST EAST CENTRE, SINGAPORE 417868			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				