

ASS. REC. BY:

REF:

TU / 22012363 / kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

1.B.1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/H 5239K

Yr Regn:

10.20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Punt

c.c

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

144816

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU303092458

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Bridon

195/65R15

R: Wards

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

8

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

8/12/22

D.O.I.

12/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/12

2513.63

Cah

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5239K

AAD2212-

*Not Authorised**Recovery B4 paint**2513.63***12 DEC 2022**~~**09 DEC 2022**~~

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC5239K

JTDKB3FU303092458

TOYOTA

PRIUS **GEN 4**

08/12/2022

SHD2633U/ II

30/10/2020

PART**LIST**

1	PANEL SUB-ASSY, REAR DOOR, RH	\$	<i>R</i>	1,294.90	<i>X</i>
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	<i>Sn</i>	193.50	<i>X</i>
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	<i>Sn</i>	97.40	<i>X</i>
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$	<i>Sn</i>	293.00	<i>X</i>
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	<i>Sn</i>	926.00	<i>X</i>
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	<i>Sn</i>	206.70	<i>X</i>
1	TAPE, BLACK OUT, NO.2 REAR RH	\$	<i>NN</i>	34.90	<i>X</i>
1	TAPE, BLACK OUT, NO.3 REAR RH	\$	<i>NN</i>	15.40	<i>X</i>
1	TAPE, BLACK OUT, NO.1 REAR RH	\$	<i>NN</i>	21.90	<i>X</i>
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	<i>R</i>	87.10	<i>X</i>
1	HINGE ASSY, REAR DOOR, UPPER RH	\$	<i>R</i>	98.90	<i>X</i>
1	PANEL SUB-ASSY, QUARTER, RH	\$	<i>B</i>	871.50	<i>✓</i>
1	LINER, REAR WHEEL HOUSE, RH	\$	<i>Sn</i>	139.80	<i>X</i>
1	COVER, REAR BUMPER	\$	<i>R</i>	485.60	<i>X</i>
1	RETAINER, REAR BUMPER SIDE, RH	\$	<i>Sn</i>	132.60	<i>X</i>

TOTAL \$ 3,269.70**25% \$ 817.43****\$ 2,452.28****Special Nett**

1	FRT FENDER LINER CLIP	\$	<i>NN</i>	65.00	<i>X</i>
1	REAR FENDER LINER CLIP	\$	<i>NN</i>	65.00	<i>X</i>
1	REAR BUMPER CLIP	\$	<i>NN</i>	65.00	<i>X</i>
1	DOOR STICKER TEL NO.	\$	<i>Ne</i>	100.00	<i>605m</i>
1	DOOR TRIM CLIP	\$	<i>NN</i>	75.00	<i>X</i>
1	DOOR WEATHERSTRIP CLIP	\$	<i>NN</i>	80.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD2212-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5239K

TOTAL	\$	450.00
TOTAL PARTS	\$	2,902.28

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	30%
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100%
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	850%
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	380.00	nn X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	800%
To reinstall rear bumper parking sensor.	\$	170.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To Check Electrical Lighting Concerned.	\$	170.00	20%
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	170.00	nn X

TOTAL \$ 5,100.00**Over All Total \$ 8,002.28**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Trans-cab Auto Services Pte Ltd

AAD2212-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5239K

(PART-BY-PART) Repair Days

05 Days

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

878K

Vehicle Details

Vehicle No.:

SHC5239K

Vehicle to be Exported:

Yes

Intended Deregistration Date:

09 Dec 2022

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS 5DR HATCHBACK (AUTO)

Primary Colour:

Red

Manufacturing Year:

2020

Engine No.:

2ZR2H09712

Chassis No.:

JTDKB3FU303092458

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$26,807.00

Original Registration Date:

30 Oct 2020

First Registration Date:

30 Oct 2020

Transfer Count:

0

Actual ARF Paid:

\$14,530.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

29 Oct 2028

PARF Rebate Amount:

\$10,897.00

Intended COE Rebate Details

COE Expiry Date:

29 Oct 2028

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$28,160.00

COE Rebate Amount:

\$20,722.00

Total Rebate Amount:

\$31,619.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 09 Dec 2022

OK