

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/12/2022

User ID : JeongCH

Section A - Accident Details

Registration Number	SG5532L
Case Reference Number	BUS/11/22/5045
Registration Date	12/19/2017
Company Type	SMRT Buses Ltd
Make	VOLVO
Model	B9TL
Name of Driver	Lim Weng Keon
Type of Accident	Side Swipe
Accident Date and Time	11/28/2022 8:00 AM
Accident Reported Date and Time	12/6/2022 12:09 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG5532L - Bus left front bumper scratches SMM6871R - AILS
Prepared Date and Time	12/8/2022 10:43 AM
Chassis Number	YV3S4P92XHA183733
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$432.00	\$0.00
Total Spare Part Cost	\$701.84	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,928.84	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	08/12/2022 10:48 AM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

