COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHC3181E

Make

: Toyota

Model : Prius (G4A)

Date: 08/12/2022 Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount	. 0
	PANEL SUB ASSY RR DOOR LH			\$ 1,258.30	XR.
	REAR DOOR OUTER HANDLE LH			\$ 95.30	/sc
	SUB TOTAL			\$ 1,353.60	
	LESS 25%			\$ 338.40	-
	DISCOUNTED TOTAL			\$ 1,015.20	1
	RENEW ADVERTISEMENT STICKER			\$ 200.00	Nett -
	RENEW ADVERTISEMENT STICKER			\$ 200.00	
	Labour Charge			700.00	250
	PANEL BEATING		*	\$ 700.00	
	SPRAY PAINTING CHARGE DOOR & RR FENDER			\$ 600.00	
	TRANSFER OF DOOR			\$ 120.00	7
	TOTAL LABOUR			\$ 1,420.00	1
	ESTIMATE TOTAL			\$ 2,635.20	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKY 8/12/2022 1625 2 DAY) AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey belons/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is the A
- Supplementary iteni(s) must be resulveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: