



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807			Ref: CS/MSG22012381/Awy3 Date: 12/12/2022 Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SCH 8182C	Veh. Inspected	SKK 5893T	
Policy No.	1002057341	Coverage (\$)	0.00	
Claim No.	293806	Excess (\$)	0.00	
Assign From	DOUGLAS ONG	Assign Date	12/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/12/2022	Inspection Date	12/12/2022	
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				