

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lee, Ming-Yao

Date: 13 Dec 2022

Preliminary Advice

Vehicle No	: SMW6651G	Accident Date	: 04/12/2022
Make	: AUDI A4	Policy No.	: 2070168460-02
Assignment Date	: 12/12/2022	Excess	: S\$0.00
Date of Inspection	: 09/12/2022	Est. Duration of Repair	: 5
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	42,817.00
Revised Amount	:S\$	18,811.00
Check Items (Estimated)	:S\$	6,506.50
Total	:S\$	25,317.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	156,000.00
COE / PARF Rebate	:S\$	60,618.00
Salvage Value	:S\$	
Margin for Repair	:S\$	95,382.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.