

# MOTOR SPORT PTE LTD

Blk 3020A Ubi Road 1, #01-35 Ubi Ind. Est. S(408714)

Tel: 67496717/8

Fax: 67416719

CR No. 199002311D

Our Ref: 09122022

Date: 9 December 2022

ECICS LIMITED

10 Eunus Road 8

#09-04A

Singapore Post Centre

Singapore 408600

*Mr Tan*  
*67418434*

To: Motor Vehicle Accident Claim Dept.

Dear Sir/Madam,

## ACCIDENT INVOLVED WITH SLH3410X AND FBJ5942Y

We will requested by our client FBJ5942Y to claim against vehicle SLH3410X which you are the insurer.

The damages is as below:-

|    |                            |    |        |               |
|----|----------------------------|----|--------|---------------|
| 1  | FRONT COVER                | \$ | 253.00 | PC <i>cut</i> |
| 2  | FRONT LH HEADLAMP COMPLETE | \$ | 412.00 | PC <i>cut</i> |
| 3  | HANDLE BAR                 | \$ | 94.00  | PC <i>3H</i>  |
| 4  | LH BRAKE LEVER             | \$ | 33.00  | PC <i>cut</i> |
| 5  | LH MIRROR                  | \$ | 126.00 | PC <i>cut</i> |
| 6  | LH BAR END                 | \$ | 14.00  | PC <i>cut</i> |
| 7  | LH SIDE SKIRT TOP          | \$ | 85.00  | PC <i>cut</i> |
| 8  | LH SIDE SKIRT BOTTOM       | \$ | 134.00 | PC <i>cut</i> |
| 9  | LH SIDE SKIRT REAR         | \$ | 122.00 | PC <i>cut</i> |
| 10 | FRONT FENDER               | \$ | 108.00 | PC <i>cut</i> |
| 11 | LEG SHIELD                 | \$ | 103.00 | PC <i>cut</i> |
| 12 | RH SIDE COVER              | \$ | 279.00 | PC <i>cut</i> |
| 13 | LH SIDE COVER              | \$ | 279.00 | PC <i>cut</i> |
| 14 | LH REAR HOLDER             | \$ | 152.00 | PC <i>dis</i> |
| 15 | LH ENGINE COVER            | \$ | 117.00 | PC <i>cut</i> |
| 16 | LH ENGINE COVER GRILL      | \$ | 30.00  | PC <i>cut</i> |
| 17 | AIR FILTER COVER           | \$ | 53.00  | PC <i>cut</i> |
| 18 | LH WINKER LAMP (LED)       | \$ | 184.00 | PC <i>cut</i> |
| 19 | METER COVER                | \$ | 35.00  | PC <i>cut</i> |
| 20 | REAR TOP BOX               | \$ | 210.00 | PC <i>cut</i> |
| 21 | SPRAY PAINTING             | \$ | 450.00 | PC <i>cut</i> |

*350*

*2823*

*10% - 2540.70.*

# MOTOR SPORT PTE LTD

Blk 3020A Ubi Road 1, #01-35 Ubi Ind. Est. S(408714)

Tel: 67496717/8

Fax: 67416719

CR No. 199002311D

Our Ref: 21122022

Date: 21 December 2022

ECICS LIMITED

10 Eunos Road 8

#09-04A

Singapore Post Centre

Singapore 408600

To: Motor Vehicle Accident Claim Dept.

Dear Sir/Madam,

## ACCIDENT INVOLVED WITH SLH3410X AND FBJ5942Y

Additional parts claim as below:-

- 1 RH BRAKE LEVER
- 2 LH FLOOR PANEL
- 3 SKIRT L SIDE
- 4 CLIP PLASTIC 7 PC @ \$2

|       |    |                 |    |           |
|-------|----|-----------------|----|-----------|
| dd ✓  | \$ | 45.00           | PC | } w4<br>X |
| ant ✓ | \$ | 58.00           | PC |           |
| dis ✓ | \$ | 33.00           | PC |           |
| pl ✓  | \$ | 14.00           | PC |           |
| TOTAL |    | <u>\$150.00</u> |    |           |

Thank you.

Tanpin 150  
10% - 135  
22/12/22

  
Herbert Teh  
Manager  
Mobile: 96638118

|             |                 |
|-------------|-----------------|
| 2540.70     | 2540.7          |
| 610         | 610             |
| <u>135X</u> | <u>        </u> |
| 3285.70     | 3150.70         |
| 4/5 @ 2600  |                 |
| 0.3 days    |                 |

# MOTOR SPORT PTE LTD

Blk 3020A Ubi Road 1, #01-35 Ubi Ind. Est. S(408714)

Tel: 67496717/8

Fax: 67416719

CR No. 199002311D

25 TOWING

26 LABOR

\$ 60.00 ✓

\$ 280.00 200


TOTAL \$3,333.00 610

We attach the SAS report for your reference.

Kindly assign your surveyor to our designated address to assess the damages.

Thank you

  
Herbert Teh  
Manager  
Mobile: 96638118



Tanplm 97415749 / 62863561  
WP' 12/12/22 @ 2pm  
tanplm @ khauto.com  
3 days  
4/5 Repair after repair.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: