



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM	M/S Grab Rentals Pte Ltd				
		Document No. 0	3 Media Close #01-03/06 Singapore 138498				
		Document Date 12/12/2022	Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	24/05/2017	SLN9807P	0	19087	75/DS/SLN9807P
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFB29F3902011497		2NRX156488	60	Ng Mei Yen	--/--/----		0.00 --/--/----
L	Cd	Job/Parts Description			Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SKX1568R ACC DATE:10/12/22 TOW IN:10/12/22 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:					50 100.00
2	B	BP-LAB2	CHEKC WIRING AND CONDUCT LEAK TEST				198.00
3	B	BP-ECU2	TO RESET ECU AND REPROGRAMME				198.00
4	B	BP-LAB2	CONDUCT WHEEL ALIGHTMENT				198.00
5	B	BP-LAB2	R/I FRONT LEFT UNDERCARRIGE				782.00
6	B	BP-LAB2	R/I FRONT LEFT DOOR COMPARTMENT				792.00
7	B	BP-LAB2	REPL ACC AFF AREA				4752.00
8	B	BP-RES2	STRAIGHTEN & PANEL BEAT ACC AFF AREA				4582.00
9	S	BP-SUBLET	RESpray ACC AFF AREA				198.00
10	1	K52119-0U920	R/I FRONT LEFT RIM			1.00	587.30
11	2	K52536-0D190	COVER, FR BUMPER, L/ de			1.00	81.80
12	3	K52128-0D250	RETAINER, FR BUMPER			1.00	71.40
13	4	K53112-0D360	COVER, FR BUMPER HOL			1.00	342.20
14	5	T52161-16010	GRILLE, RADIATOR, LW			10.00	49.00
			PIECE, RR BUMPER				53.00
For & on behalf of		Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
						Amount Due	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd				
		Document No. 0		3 Media Close #01-03/06 Singapore 138498				
		Document Date 12/12/2022		Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	NSP151R	CEXRKT Q1	24/05/2017	SLN9807P	0	19087	75/DS/SLN9807P	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MHFB29F3902011497		2NRX156488	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
15	6	K53812-K0020	PANEL, FR FENDER, LH	1.00	836.90		836.90	
16	7	K53828-0D160	PROTECTOR, FR FENDER	1.00	57.90		57.90	
17	8	K53867-0D160	SEAL, FR FENDER TO C	1.00	54.60		54.60	
18	9	K53876-0D380	LINER, FR FENDER, LH	1.00	361.10		361.10	
19	0	K53702-0D190	APRON SUB-ASSY, FR F	1.00	707.10		707.10	
20	1	K48069-09340	ARM SUB-ASSY, SUSPEN	1.00	1453.60		1453.60	
21	2	K48510-0DC40	ABSORBER ASSY, SHOCK	1.00	498.90		498.90	
22	3	K67002-0D160	PANEL SUB-ASSY, FR D	1.00	1355.10		1355.10	
23	4	K67832-0D360	COVER, FR DOOR SERVI	1.00	43.10		43.10	
24	5	K68151-0D230	RUN, FR DOOR GLASS,	1.00	145.60		145.60	
25	6	K67404-0D160	FRAME SUB-ASSY, FR D	1.00	120.20		120.20	
26	7	K67862-0D210	WEATHERSTRIP, FR DOO	1.00	243.50		243.50	
27	8	K67924-0D120	CUSHION, FR DOOR STI	1.00	62.70		62.70	
28	9	K75922-0D170	TAPE, BLACK OUT, NO.	1.00	57.20		57.20	
29	0	K60118-0D170	COVER SUB-ASSY, FR P	1.00	37.90		37.90	
30	1	K87940-0D740	MIRROR ASSY, OUTER R	1.00	1496.60		1496.60	
31	2	K87945-0D919	COVER, OUTER MIRROR,	1.00	129.50		129.50	
32	3	K81150-0D831	HEADLAMP ASSY, LH	1.00	722.00		722.00	
33	4	K61404-0D230	REINFORCE SUB-ASSY,	1.00	651.50		651.50	
34	5	K42611-0DC00	WHEEL, DISC	1.00	2311.40		2311.40	

Handwritten notes:
 Resue
 Hp 90010068
 8 days 12
 12/12/22 @ 1520
 Resue before paint

For & on behalf of		Customer's Signature	Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts	12,482.10	GST 7.00% 1,701.15 Less 0.00 Amount Due 26,003.25
			Labour	11,622.00	
			Sublet	198.00	
			Lubrication/Fluid	0.00	
			Others	0.00	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
Onpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	M/S Grab Rentals Pte Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 02/03/2023	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	NSP151R	CEXRKT Q1	24/05/2017	SLN9807P	0	19087	75/DS/SLN9807P

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MHFB29F3902011497	2NRX156488	60	Ng Mei Yen	12/12/2022 8.00	27/12/2022 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	1	K45510-0D551 GEAR ASSY, STEERING <i>bt</i>	1.00	2327.30		2327.30
2	2	S48510-0DC40 ABSORBER ASSY, SHOCK <i>H</i>	1.00	498.90		498.90
3	3	S43212-0D250 KNUCKLE, STEERING, L <i>bt</i>	1.00	789.30		789.30
4	4	S48069-09340 ARM SUB-ASSY, SUSPEN <i>bt</i>	1.00	1453.60		1453.60
5	5	K51201-0D180 CROSSMEMBER SUB-ASSY <i>bt</i>	1.00	2258.40		2258.40
6	6	K43560-0D050 HUB & BRG ASSY, FR A <i>bt</i>	1.00	708.50		708.50
7	7	K45047-09390 END SUB-ASSY, TIE RO <i>bt</i>	1.00	200.30		200.30
8	8	T68740-12120 HINGE ASSY, FR DOOR, <i>bt</i>	1.00	133.20		133.20
9	9	S68720-0K020 HINGE ASSY, FR DOOR, <i>bt</i>	1.00	117.20		117.20
10	0	S61132-0D170 PILLAR, FR BODY, UPR <i>bt</i>	1.00	421.40		421.40
11	1	S67862-0D210 WEATHERSTRIP, FR DOO <i>ne</i>	1.00	245.80		245.80
12	2	K55550-0D270 C0 DOOR ASSY, GLOVE COM <i>cn</i>	1.00	765.80		765.80

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts 9,919.70	9,919.70
		Labour 0.00	GST 7.00% 640.77
		Sublet 0.00	GST 8.00% 61.26
		Lubrication/Fluid 0.00	Less 0.00
		Others 0.00	Amount Due 10,621.73

Customer Copy