

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III22012419/APA3Q2**Date:** 20/07/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0000191\_03

**Claimant Vehicle No :** SMU6168X **Insured Vehicle No :** GBB7713X

Date of Loss: 09/12/2022 Nature of Claim: TP Claim No: MFL2022D0011575

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMU6168X**  
 Make & Model: HONDA CIVIC, 1.6 VTI CVT (A) Engine No: R16B25520045  
 Reg. Date: 21/08/2020 (Man. Year: 2020) Chassis No: MRHFC5650LT000010  
 Colour: White Odometer: 54601 km  
 Engine Capacity: 1597 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

**CONDITION OF TYRES**

Front Tyre Size: 235/40 R18 Rear Tyre Size: 235/40 R18  
 Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm  
 Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>4,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>4,100.00</b>	<b>-4,100.00</b>	
<b>+ Car Rental (6.0 x S\$100.00/day) (S\$)</b>		600.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,707.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,700.00</b>		

**INSPECTION**

Date of Assignment: 12/12/2022

Date Inspected: 13/12/2022 Inspected At: Kt Motorwerk (HQ)  
 Blk 3012 Bedok Industrial Park E, #01-2020  
 Singapore 489978

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jun 2023)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU6168X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >