

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	09 Dec 2022 16:37	Clm Veh Model Changed		[] Merimen Administrator
2	09 Dec 2022 16:37	Clm Created	Reg No: SCR17Y. Policy No: 1900171773. Acct Date: 2022/12/09. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP1 422C90001	[I] Merimen Administrator
3	13 Dec 2022 12:47	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] Rajeswari
4	13 Dec 2022 12:47	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] Rajeswari
5	13 Dec 2022 12:47	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Rajeswari
6	13 Dec 2022 12:47	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/12/22	[A] Rajeswari
7	13 Dec 2022 12:47	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Rajeswari
8	13 Dec 2022 12:47	Clm Registration Modified	Rep:1137->200611.	[A] Rajeswari
9	13 Dec 2022 12:47	Clm Veh Model Changed	(200049) AUDI A6 2.0 TFSI (A).	[A] Rajeswari
10	13 Dec 2022 12:48	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] Rajeswari
11	13 Dec 2022 15:48	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
12	13 Dec 2022 15:48	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
13	13 Dec 2022 15:48	Clm Dtl Modified	JPJ Reg. Date: -> 2019/10/29.	[A] Elaine Kuan Hwa Meen
14	13 Dec 2022 15:48	Clm Details Notified		[A] Elaine Kuan Hwa Meen
15	13 Dec 2022 16:19	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/12/22	[A] SHIAU CHAN
16	13 Dec 2022 16:20	Adj Mandate Request	Cur.Req:22626.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUT HORISE REPAIR.	[A] SHIAU CHAN
17	13 Dec 2022 17:29	Clm Registration Modified	Init.Est.:->5,000 - 6,000. Excess: -> 0.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Azlan, Syazairdina
18	15 Dec 2022 11:33	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/12/22. Mandate Remarks: Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair	[I] Lim, Kok-Chong
19	15 Dec 2022 11:33	Adj Mandate Set	Approved:19811.00:Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong

Date From   
 Date To   
 Audit Type 

ACTIVITY

No record

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2883083	13 Dec 2022 15:48:33	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SCR17Y		11.00

