

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LIBERTY INSURA	NCE PTE LTD	Ref:	CS/LIP22012467/Uqy3e2	
	51 CLUB STREET LIBERTY HOUSES	, #03-00 SINGAPORE 069428	Date:	02/02/2023	
			Code:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLU 243M	Veh. Inspected	SLJ 76L	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	IVS22/2202	Excess (\$)	0.00	
	Assign From	ANDY SEAH	Assign Date	09/01/2023	
2.	Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E220 CDI AMG (A)	c.c	1950	
	Engine No.	HIDDEN	Year of Reg.	0	
	Chassis No.	WDD2130042A297596	Colour	WHITE	
	Odometer	80227 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	245/35Z R20	GOODYEAR	6 mm	
	L/H Front Tyre	245/35Z R20	GOODYEAR	6 mm	
	R/H Rear Tyre	275/30Z R20	GOODYEAR	6 mm	
	L/H Rear Tyre	275/30Z R20	GOODYEAR	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	10/12/2022	Inspection Date	19/12/2022	
	Survey held at	FALCON-AIR AUTO SERVICES	PTE LTD		
		BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840			
5a.		Remarks			
	A)REGISTRATION DATE: 03 NOV 2017 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			