



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KITTY		Ref: CC4/ASM22012475/Gpa3q2 Date: 06/07/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 9046T	Veh. Inspected	SKK 6366S
Policy No.	P2477626	Coverage (\$)	0.00
Claim No.	S2M04GBU	Excess (\$)	0.00
Assign From		Assign Date	13/12/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA NOAH HYBRID	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	ZWR800357606	Colour	PURPLE
Odometer	101798 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R16	TOYO	4 mm
L/H Front Tyre	215/55 R16	TOYO	4 mm
R/H Rear Tyre	215/55 R16	TOYO	5 mm
L/H Rear Tyre	215/55 R16	TOYO	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/12/2022	Inspection Date	13/12/2022
Survey held at	AUBURN AUTO PTE LTD 176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	