

Date: 13/12/2022

Vehicle No: SNA5292U

Model: TOYOTA PRIUS 5DR HATCHBACK

Chassis: JTDKB3FU103091910 - 2020

Reg.Year: 2021

Third Party Insurer: AIG

Third Party Veh No: SKK6868K

Date of Accident: 10/12/2022

Estimator: KIT

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP LH	1	ME	\$2,852.00
2	FRONT BUMPER	1	Bu	\$665.00
3	FRONT BUMPER SIDE RETAINER LH	1	DIT	\$80.00
4	FRONT FENDER LH	1	R1	\$988.00
5	FRONT FENDER "HYBRID" EMBLEM LH	1	ME	\$66.00
6	FRONT FENDER QUARTER GARNISH LH	1	ME	\$94.00
7	FRONT FENDER INNER SHIELD LH	1	DIT	\$202.00
8	FRONT DOOR LH	1		REPAIR
9	FRONT RIM LH	1		REPAIR
SUB TOTAL				\$4,947.00
LESS 25%				-\$1,236.75
PARTS TOTAL				\$3,710.25

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1	ME	\$50.00
2	FRONT FENDER INNER SHIELD CLIPS LH	1	ME	\$30.00
S/N TOTAL				\$80.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST AT ACCIDENT AREAS.	\$500.00	400
LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS.	\$500.00	400
LABOUR CHARGES TO FRONT WHEEL ALIGNMENT & BALANCING.	\$100.00	60
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$80.00	30
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$80.00	20

LABOUR TOTAL \$1,260.00

KIT TOTAL \$5,050.25

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

