

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIS22012491/TNY3M4**Date:** 19/12/2022REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No:

**Claimant Vehicle No :** SJR4561H**Insured Vehicle No :** SMM5809D

Date of Loss: 11/12/2022

Nature of Claim: TP

Claim No: ABRAISCL2022-00012KC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJR4561H**

Make &amp; Model: MITSUBISHI LANCER, 1.6 CVT SPORTS GLX (A)

Engine No: 4G18KC6666

Reg. Date: 25/06/2009 (Man. Year: 2009)

Chassis No: JMYSTCS3A9U005638

Colour: Silver

Odometer: 145082 km

Engine Capacity: 1584 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>              | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                              | 0.00              | 0.00              | 0.00              |               |
| Miscellaneous Items                | 0.00              | 0.00              | 0.00              |               |
| Labour                             | 0.00              | 0.00              | 0.00              |               |
| Paintwork Labour                   | 0.00              | 0.00              | 0.00              |               |
| Towing                             | 0.00              | 0.00              | 0.00              |               |
| <b>Nett Amount (S\$)</b>           | <b>0.00</b>       | <b>0.00</b>       | <b>0.00</b>       |               |
| <b>Global Sum Settlement (S\$)</b> |                   | <b>0.00</b>       |                   |               |

INSPECTION

Date of Assignment: 13/12/2022

Date Inspected: 14/12/2022

Inspected At:

PRECISE AUTO SERVICE

NO.1 KAKI BUKIT AVE 6

#02-34/36 , SINGAPORE 417883

Estimated Period of Repair: 7.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00  
-\$6,000.00

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                                            |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                                            |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 19 Dec 2022)                              |
| Parts:        | 143                                                                                                                                                                          | MITSUBISHI LANCER 1.6 CVT SPORTS GLX (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                          |
| Print Code:   | (Unsubmitted, no print-code for SJR4561H)                                                                                                                                    |                                                                            |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                            |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                            |

Recommended Parts

There are no new parts selected.

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >