

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	HSBC LIFE (SING)		Ref:	CS/ASM22012522/Kwp3e2	
	10 MARINA BOUL	EVARD AY FINANCIAL CENTRE TOWER	Date	·	
	ATTN: OH VALE		Code	: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHC 7614Y	Veh. Inspected	SND 9833S	
	Policy No.	VFX/P2419140	Coverage (\$)	0.00	
	Claim No.	S2M04GG0	Excess (\$)	0.00	
	Assign From	OH VALE	Assign Date	14/12/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA NOAH (A)	c.c	1797	
	Engine No.	HIDDEN	Year of Reg.	2022	
	Chassis No.	ZWR800504435	Colour	METALLIC BLACK	
	Odometer	75811 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	FARROAD	7 mm	
	L/H Front Tyre	195/65 R15	FARROAD	7 mm	
	R/H Rear Tyre	195/65 R15	GOODYEAR	8 mm	
	L/H Rear Tyre	195/65 R15	GOODYEAR	8 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	09/12/2022	Inspection Date	19/12/2022	
	Survey held at	160 SIN MING DRIVE #08-13 SII	N MING AUTOCITY		
	Repairer AERO GARAGE PTE LTD				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				