

(08/11/23)

ASS. REC. BY:

REF:

CS | SMR 22012545 | Dny³

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 200 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ 5982 M Yr Regn: Dec / 2016Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mitsubishi Lancer Ex c.cColour: Blue A/C: Insured / Std / NI / NASp. Reading: 135833 T/Radio: Insured / Std / NI / NAEng/No: 4A92CL8469C/No: JMYSRCS2AGU006106Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60 R16R: — 11 —BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Achilles

Front

Rear

R/Bal. S mm R/Bal. S mmL/Bal. S mm L/Bal. S mmD.O.A. 12/12/22 D.O.I. 16/12/22Survey held at Hup Man TemplesDes. of Damages: o/s front / Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SMRT STD. 6298C

16/01/23 From HS 22001 - with 3 days of rep

(Red. \$ 2440.25, 53%)

Date/Time, File Pass to?

1) 16/1/23

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : TPLump Sum / I.B.I.: (\$ 2200)

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3096/12/22 Your Ref: Date: 14th DEC 2022

HAIRULISYAM BIN NORISHAM
BLK 885A, #07-129,
Tampines Street 83
Singapore 521885

Estimate cost of repair to MITSUBISHI LANCER EX 1.6 (A) Saloon - SLJ 5982 M

1 pc front o/s fender <i>den</i>		\$ 588.00	X
1 pc front o/s fender inner shield <i>sn</i>		107.00	X
8 pcs front o/s fender inner shield clips <i>nn</i>	@ \$ 3.50	28.00	X
1 pc front bumper <i>cut</i>		985.00	✓
10 pcs front bumper clips <i>hlc</i>	@ \$ 3.50	35.00	X ✓
1 pc front bumper o/s side retainer <i>nn</i>		28.00	X
1 pc front bumper o/s side bracket clips <i>nn</i>		5.50	X
1 pc front bumper o/s fog lamp assy <i>nn</i>		426.00	X
1 pc o/s head lamp assy <i>cut / money broken</i>		698.00	✓
1 pc o/s head lamp lower retainer <i>nn</i>		22.00	X
		<u>\$ 2,922.50</u>	
	Less 10%	\$ 292.25	
		<u>\$ 2,630.25</u>	

To wiring check up & adjust headlight alignment.

~~50.00~~ 30/-

To check & adjust front wheel alignment & balancing.

150.00 *nn*

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front support panel, head lamp panel & necessary parts, to weld, renew & align above parts.

1210.00

~~800.00~~ 550/-

To putty & respray painting on all affected accident parts.

~~950.00~~ 600/-

To respray Tuff-Kote on all affected accident parts.

~~60.00~~ 30/-

\$ 4,640.25

=====

Dollars : Four Thousand Six Hundred Forty And Cents Twenty Five Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

16/12/2022 @ 1030m

Hat Auto

2 Hour 3 day..

nn

2Kk Auto

2756.20

4/5 2,200/-