

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: **AIG Asia Pacific Insurance Pte. Ltd.**
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: **LKK Auto Consultants Pte Ltd**
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 15 Dec 2022

Preliminary Advice

Vehicle No	: SNF3268C	Accident Date	: 09/12/2022
Make	: AUDI A5	Policy No.	: 7220055041
Assignment Date	: 15/12/2022	Excess	: S\$0.00
Date of Inspection	: 14/12/2022	Est. Duration of Repair	: 4
Inspection At	: PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,500.00
Revised Amount	:S\$	2,402.00
Check Items (Estimated)	:S\$	400.00
Total	:S\$	2,802.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	245,000.00
COE / PARF Rebate	:S\$	123,031.00
Salvage Value	:S\$	
Margin for Repair	:S\$	121,969.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .