



Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLP11		Mr Lim Chee Boon		
			Document No. 0		393 Bukit Batok West Avenue 5 #04-464 Singapore 650393		
			Document Date 15/12/2022		Mobile: 98628013		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZGE20R	HPXNP S6	17/10/2016	SLG8724M	0	19146	77/DS/SLG8724M
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In	Collected On	
JTDGG20W20J005575		2ZR1844220	60	Cheng Wei Ting	0.00	--/--/----	
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES ACC DATE: 15/12/22 TP VEH: XE7892K DATE-IN: DATE SURVEY: NO OF REPAIR DAYS:				50	108.00
2	B	BP-LAB2 TO DRILL HOLE AND INSTALL REAR SENSOR				198	180.00
3	B	BP-LAB2 TO CHECK WIRING AND CARRY OUT WATER LEAK TEST				134.64	122.40
4	B	BP-MECH2 TO CARRY OUT WHEEL BALANCING AND REPLACE TYRE RIM				72.00	
5	B	BP-MECH2 TO CARRY OUT WHEEL ALIGNMENT				180.00	
6	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198	180.00
7	B	BP-WS2 TO REMOVE AND INSTALL REAR RHS QUATER GL ASSFOR REPAIR				396	231.00
8	B	BP-LAB2 TO REMOVE INTERIOR UPHOLESTRY				792	720.00
9	B	BP-LAB2 TO REPAIR AND REPLACE ON ACCIDENT AFFECT EDAREA				3168	3600.00
10	B	BP-RES2 TO SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREA				1968	2360.00

ASK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due



LKK Auto Consultants hereby notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____
Date: _____

Customer Details

ESTIMATE

Account Details		Account No. S1000007 / ICLP11	Mr Lim Chee Boon	
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		Document No. 0	393 Bukit Batok West Avenue 5 #04-464 Singapore 650393	
		Document Date 15/12/2022	Mobile: 98628013	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZGE20R	HPXNP S6	17/10/2016	SLG8724M	0	19146	77/DS/SLG8724M

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDGG20W20J005575	2ZR1844220	60	Cheng Wei Ting	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	S	BP-SUBLET TO SUPPLY & INSTALL QUATER GLASS 3M SOLAR <i>photo?</i>				190.00
12	1	FILM	1.00	108.00		108.00
13	2	SIKA 182010 SIKI TACK GO! (BLA <i>neu</i>)	1.00	200.00		200.00
14	3	SIKA 207. G+P ADHESIVE PRIMER <i>neu</i>	1.00	267.20		267.20
15	4	PANEL BONDING AD <i>neu</i>	1.00	4.90		49.00
16	5	PIECE, RR BUMPER <i>neu</i>	10.00	4.90		49.00
17	6	WINDOW ASSY, <i>neu photo</i>	1.00	492.70		492.70
18	7	PANEL SUB-ASSY, <i>neu photo</i>	1.00	1286.40		1286.40
19	8	TROUGH, BACK DOOR OP <i>neu</i>	1.00	97.10		97.10
20	9	PLATE, RR BUMPER <i>neu</i>	1.00	710.20		710.20
21	0	EXTENSION, RR <i>neu</i>	1.00	80.50		80.50
22	1	SUPPORT, RR BUMPER S <i>neu</i>	1.00	117.20		117.20
23	2	RETAINER, RR BUMPER <i>neu</i>	1.00	55.30		55.30
24	3	PAD, RR BUMPER, RH <i>neu</i>	2.00	6.50		13.00
25	4	PAD, RR BUMPER, RH <i>neu</i>	2.00	6.50		13.00
26	5	MOULDING, QUARTER <i>neu</i>	1.00	46.50		46.50
27	6	MOULDING, QUARTER <i>neu</i>	1.00	46.50		46.50
28	7	WHEEL, DISC <i>neu</i>	1.00	2196.90		2196.90
29	8	LENS & BODY, RR <i>neu</i>	1.00	353.40		353.40
		LENS & BODY, RR <i>neu</i>	1.00	425.90		425.90

Resur
Hp 90010067
8 days
07/02/23 @ 12:20
Resy before print

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	14,494.20
	Please acknowledge receipt of vehicle	Parts	GST 7.00%	1,014.59
		Labour	Less	0.00
		Sublet		
		Lubrication/Fluid	Amount Due	15,508.79
		Others		