



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 62504489 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2212-676-TG

DATE : 15-Dec-2022

POLICY NO. :

VEHICLE REG. NO. : SMG2438S

VEHICLE MAKE : RENAULT / GRAND SCENIC IV 2018

VF1RFA00361789211

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

Rasul - Hp 90010068

S days - L/S

15/12/22 @ 1430

Rey after repair

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Door LH <i>buc</i>	1	\$ 2,400.00	\$ 2,400.00
2	Rear Door Weatherstrip LH <i>m</i>	1	\$ 310.00	\$ 310.00
3	Rear Door Upper Moulding Chrome LH <i>? X n</i>	1	\$ 400.00	\$ 400.00
4	Rear Door Rear Black Cover LH <i>m</i>	1	\$ 300.00	\$ 300.00
5	Rear Door Front Black Cover LH <i>m</i>	1	\$ 300.00	\$ 300.00
6	Rear Door Bottom Garnish With Chrome LH <i>guc</i>	1	\$ 630.00	\$ 630.00
7	Rear Door Upper Hinge LH <i>? X n</i>	1	\$ 320.00	\$ 320.00
8	Rear Door Bottom Hinge LH <i>? X n</i>	1	\$ 320.00	\$ 320.00
9	Rear Fender LH <i>repair X A</i>	1	\$ 3,100.00	\$ 3,100.00
10	Rear Fender Shield LH <i>X n</i>	1	\$ 350.00	\$ 350.00
11	Rear Fender Clips <i>m</i>	10	\$ 5.00	\$ 50.00
12	Sill Panel LH <i>guc</i>	1	\$ 1,000.00	\$ 1,000.00
Total Spare Parts				\$ 9,480.00
SPECIAL NETT				
Total Special Nett				\$ -
LABOUR				
13	Spray Painting Rear Door LH, Side Sill, Rear Fender, and Rear Bumper Including Blending	1	\$ 1,200.00	\$ 1,200.00
14	Remove, Refit and Repair Affected Accident Parts	1	\$ 1,400.00	\$ 1,400.00
15	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 100.00	\$ 100.00
16	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,730.00
Amount Before Excess				\$ 12,210.00
Add GST @ 7%				854.70
Total Amount Payable				\$ 13,064.70

Estimate prepared by: RAZALI

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4491

1290

5781

20%

4624.80

L/S - \$4600 / 5 days

600

600

60

1290