

The Motor Claims Department
M/s Lorpac Insurance Bhd
100 Beach Road
#19-00 Shaw Tower
Singapore 189702



File No: SH/2022/330/12/014/OD
Date: 19-December-2022

Supplementary estimated cost of repair for vehicle no: SKX1568R Audi A3
Policy No: =EstimateRC Accident Date: 10.12.2022

Description	Quantity	Cost Price
-------------	----------	------------

Bonnet lock cable	✓ 30 m	
Front right headlamp ECU	7 m x	
Front left headlamp ECU	7 m x	