

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	STRIDES AUTOM	OTIVE SERVICES PTE LTD	Ref	= 1	
		INDUSTRIAL PARK	Dat	1 e: 28/12/2022	
	E4SINGAPORE 75	57705		. 0115	
_			Cod		
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 1699Y	Veh. Inspected	FBR 2342G	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	TAX/08/22/2050	Excess (\$)	0.00	
	Assign From	ANA MAGNAYE	Assign Date	15/12/2022	
2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA FZS	C.C	149	
	Engine No.	HIDDEN	Year of Reg.	2020	
	Chassis No.	ME1RG44B8K0052959	Colour	BLUE	
	Odometer	26904 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	110/70-17	PIRELLI	5 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	130/70-17	PIRELLI	5 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	17/08/2022	Inspection Date	25/08/2022	
	Survey held at	BROTHER MOTORS			
		BLK 1016 YISHUN INDUSTRIAL PARK A #01-218 SINGAPORE 768758			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				