



## Final Report

Estimate No. : **b1 63840**  
Date Estimated : **29/10/2022**  
Prepared By : **Yap Mee Key**

Page No. :

**- ESTIMATE REPAIR FOR -**

**Ram Mohan Seth**  
**35 Dunbar Walk**

**Singapore 459327**

**- ACCOUNT - 135**

**China Taiping Insurance (S) Pte Ltd**  
**3 Anson Road**  
**#16-00 Springleaf Tower**  
**Singapore 079909**

|                 |                          |                   |                      |              |
|-----------------|--------------------------|-------------------|----------------------|--------------|
| REGN. NO.       | CHASSI S NO.             | REGN. DATE        | MODEL                | M LEAGE      |
| <b>SGA5554Y</b> | <b>WBA7H62080BL02290</b> | <b>26/06/2018</b> | <b>M760Li XDRIVE</b> | <b>39435</b> |

| DESCRIPTION                                                                                      | ORIGINAL PRICE | DISC. % | NETT    |      |
|--------------------------------------------------------------------------------------------------|----------------|---------|---------|------|
| To make good front RH fender include carrying out necessary repairs casued by the accident       | 850.00         |         | 850.00  |      |
| To respray front RH fender                                                                       | 885.00         |         | 885.00  |      |
| To check electrical electrical wiring system and lightings at the RH section for proper function | 168.00         |         | 168.00  |      |
| Sundries                                                                                         | 40.00          |         | 40.00   |      |
| DESCRIPTION                                                                                      | UNIT PRICE     | QTY     | DISC. % | NETT |

# SUPPLEMENTARY ITEMS

|                                     |          |
|-------------------------------------|----------|
| Total Labour :                      | 1,943.00 |
| Total Parts :                       |          |
| Total Labour & Parts (before GST) : | 1,943.00 |
| Deduction for Excess :              |          |
| Total Repair Costs less Excess:     | 1,943.00 |
| GST @8%:                            | 155.44   |
| Grand Total :                       | 2,098.44 |

**Performance Motors Limited.**

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269  
Co Reg No. 197401559W

