

Your Ref : SNM22D208924/C01

Date: 18th January 2023

Our Ref : CS/CTI22012574/Gqp3m4

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE XE 253B
ACCIDENT ON 10/12/2022**

Instruction was received to inspect the vehicle Reg. No. XE 253B. The inspection was conducted on 16/12/2022 at the premises of M/s Auto Insure Pte Ltd, 6 Marsiling Lane, Singapore 739145.

The following vehicle information was recorded:

Registration Number	: XE 253B
Make/Model	: Isuzu FVR34UUQDC
Year of Registration	: 2015
Body Colour	: White
Chassis Number	: JALFVR347E7000717
Engine Capacity	: 7790 cc

The vehicle sustained damages at the front portion and n/s body. The undercarriage affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 56,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 11,297.00)
Nett Liability	<u>S\$ 44,703.00</u> =====

Vehicle Inspected By:



XING GUO QIANG
M.MATAI, AMSAE-A
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.